

		XS	S	M	L	XL	XXL
		(A) Breast circumference	74-88	80-94	86-105	92-112	100-124
(B) Circumference under the breast	58-72	64-78	70-84	76-92	84-102	92-116	

How To Use The Circumference Measuring Chart

A - Circumference of your breasts

B - Circumference under the breast

Measuring For the Compression Women's Legging

- Use a cloth measuring tape
- Take measurements on bare skin in centimeters
- Lay tape flat and keep snug without creating indentations
- Measure the circumference point in the diagram
- Compare your measurement to the chart